

# Figure 1

## PAHSIMEROI RIVER PROJECT AREA

This sketch shows conditions BEFORE PROJECTS (2007-2009)

Sulphur Creek was blocked in this area



Duck Creek was blocked at Cross Ditch



Muddy Springs Creek was blocked at P-9 Ditch



Flow in this area was very low: 2 to 5 cfs

Redds above Cross Ditch: 2 in 2008

- River or Creek
- Dry creek bed (due to blockage)
- Ditch

